## Thru-Spindle Air Blast

For applications requiring air flow though the spindle, to clear chips or to eject finished parts, this option is ideal.

Uses the same drawtube and rotary union as thru-spindle coolant option, insuring maximum air flow to the collet.

The air valve has Cv of 1.99, which provides maxium theoretical flow of 90cfm at 80psi.

